



CESA: 10 *Number of schools reported for CESA 10: 77*

Which best describes the location of your school building?

0	0.00%	Large Central City (Population greater than 400,000 and density greater than 6,000.)
0	0.00%	Mid-Size Central City (Population less than 400,000 and density less than 6,000.)
0	0.00%	Urban Fringe of Large City (Defined as urban by the Census Bureau.)
35	45.45%	Urban Fringe of Mid-Size City (Defined as urban by the Census Bureau.)
0	0.00%	Large Town (Population greater than or equal to 25,000.)
6	7.79%	Small Town (Population less than 25,000 and greater than or equal to 2,500.)
36	46.75%	Rural (Population less than 2,500 and coded rural by the Census Bureau.)

A. PHYSICAL STRUCTURE AND MECHANICAL FEATURES

4. *When was the school originally constructed?*

Pre-1900	0	0.00%	1930-1939	5	6.49%	1970-1979	9	11.69%
1900-1909	3	3.90%	1940-1949	2	2.60%	1980-1989	5	6.49%
1910-1919	3	3.90%	1950-1959	23	29.87%	1990-1999	8	10.39%
1920-1929	1	1.30%	1960-1969	18	23.38%			

5. *In your opinion, is this school building overcrowded?*

Yes	17	22.08%	No	60	77.92%
-----	----	---------------	----	----	---------------

6. *If the original building has been renovated or had additions, when was the most recent, MAJOR renovation or addition?*

No Renovation	20	25.97%	1940-1949	0	0.00%	1970-1979	3	3.90%
Before 1930	1	1.30%	1950-1959	1	1.30%	1980-1989	3	3.90%
1930-1939	0	0.00%	1960-1969	3	3.90%	1990-1999	46	59.74%

7. *How many total square feet does the original building have?*

Minimum:	2,500	Maximum:	237,700	Median:	43,653	Average:	59,851
----------	-------	----------	---------	---------	--------	----------	--------

8. *If the building has been renovated or added on to, how many total square feet exist now?*

Minimum:	10,800	Maximum:	305,000	Median:	56,450	Average:	84,806
----------	--------	----------	---------	---------	--------	----------	--------

9. *How many portable classrooms were in use during the 1998-99 school year?*

Number of schools reporting the use of portable classrooms: 5

Minimum:	1	Maximum:	2	Median:	1	Average:	1
----------	---	----------	---	---------	---	----------	---

10. *Does the school accommodate any of its students in instructional facilities located OFF-SITE?*

Yes	3	3.90%	No	74	96.10%
-----	---	--------------	----	----	---------------

11. *How many of this school's FTE students are located in OFF-SITE facilities?*

Number of schools reporting OFF-SITE facilities: 3

Minimum:	6	Maximum:	57	Median:	10	Average:	24
----------	---	----------	----	---------	----	----------	----

CESA: 10

Number of schools reported for CESA 10: 77

Definitions for questions #12 and #15:**Excellent:** New or easily restorable to "like new" only minimal routine maintenance.**Good:** Only routine maintenance or minor repair required.**Adequate:** Some preventive maintenance and/or corrective repair required.**Fair:** Fails to meet code and functional requirement in some cases; extensive repair.**Poor:** Consistent substandard performance; major corrective repair or overhaul.**Replace:** Non-operational or significantly substandard performance. Replacement**NA:** Not Applicable**12. What is the overall condition of the original buildings and the permanent additions?**

	Excellent	Good	Adequate	Fair	Poor	Replace	NA
Original Buildings:	16 20.78%	25 32.47%	27 35.06%	4 5.19%	4 5.19%	1 1.30%	0 0.00%
Permanent Additions:	17 22.08%	25 32.47%	14 18.18%	1 1.30%	0 0.00%	1 1.30%	19 24.68%

13. What would be the total cost of all repairs/renovations/modernizations required to put this school's ON-SITE buildings in good overall condition?Number of schools reporting cost for repairs/renovations/modernizations: **40**CESA Total Costs = **\$69,663,000**

Minimum: \$8,000 Maximum: \$15,000,000 Median: \$500,000 Average: \$1,741,575

14. On which of the sources listed below is this estimate based? Choose all that apply.

32	26.23%	Does not apply--already in good (or better) overall condition.
20	16.39%	Facilities inspection/assessment performed within the last three years by licensed professionals.
15	12.30%	Repair/renovation/modernization work already being performed/contracted for.
11	9.02%	Capital improvement/facilities master plan or schedule.
36	29.51%	My best professional judgement.
8	6.56%	Opinions of others.

15. Overall, what is the physical condition of each of the building features listed below for this school's ON-SITE buildings?

	Excellent	Good	Adequate	Fair	Poor	Replace
Roofs:	23 29.87%	44 57.14%	7 9.09%	2 2.60%	1 1.30%	0 0.00%
Framing, floors, foundations:	26 33.77%	30 38.96%	18 23.38%	1 1.30%	2 2.60%	0 0.00%
Exterior walls, finishes, windows, doors:	19 24.68%	23 29.87%	26 33.77%	8 10.39%	1 1.30%	0 0.00%
Interior finishes, trims:	15 19.48%	31 40.26%	27 35.06%	3 3.90%	1 1.30%	0 0.00%
Plumbing:	17 22.08%	23 29.87%	27 35.06%	3 3.90%	7 9.09%	0 0.00%
Heating ventilation, air conditioning:	15 19.48%	21 27.27%	24 31.17%	10 12.99%	6 7.79%	1 1.30%
Electrical power:	19 24.68%	25 32.47%	22 28.57%	8 10.39%	3 3.90%	0 0.00%
Electrical lighting:	21 27.27%	31 40.26%	18 23.38%	5 6.49%	2 2.60%	0 0.00%
Life safety requirements (e.g., emergency lighting and warning systems, exit signs):	20 25.97%	30 38.96%	19 24.68%	4 5.19%	3 3.90%	1 1.30%

CESA: 10

Number of schools reported for CESA 10: 77

16. How adequate is your current maintenance budget for keeping your buildings in good overall condition?

Very Adequate:	12	15.58%	Somewhat Adequate:	35	45.45%
Adequate:	22	28.57%	Not adequate at all:	8	10.39%

17. How satisfactory or unsatisfactory is each of the following environmental factors in this school's ON-SITE buildings?

	Very Satisfactory	Satisfactory	Unsatisfactory	Very Unsatisfactory
Lighting:	28 36.36%	42 54.55%	7 9.09%	0 0.00%
Heating:	22 28.57%	49 63.64%	5 6.49%	0 1.30%
Ventilation:	18 23.38%	44 57.14%	14 18.18%	1 1.30%
Indoor air quality:	20 25.97%	46 59.74%	10 12.99%	1 1.30%
Acoustics for noise control:	13 16.88%	56 72.73%	8 10.39%	0 0.00%
Flexibility of instructional space:	15 19.48%	47 61.04%	14 18.18%	1 1.30%
Energy efficiency/conservation:	17 22.08%	48 62.34%	12 15.58%	0 0.00%
Physical security of buildings:	9 11.69%	47 61.04%	17 22.08%	4 5.19%
Exterior noise:	24 31.17%	47 61.04%	6 7.79%	0 0.00%

18. How many instructional classrooms were in use as of the third Friday in September, 1998?

Total number of instructional classrooms reported in use as of the third Friday in September, 1998: 2,289

Minimum:	10	Maximum:	100	Median:	26	Average:	30
----------	----	----------	-----	---------	----	----------	----

19. Does the school building have CENTRAL air conditioning (cools all interior space)?

Yes	18	23.38%	No	59	76.62%
-----	----	--------	----	----	--------

20. Does this school have air conditioning in instructional classrooms, computer labs, and/or the library?

23 30.67% Yes, in instructional classrooms.

30 40.00% Yes, in computer labs.

22 29.33% Yes, in the library.

21. How many instructional classrooms have air conditioning?

Minimum:	1	Maximum:	20	Median:	4	Average:	6
----------	---	----------	----	---------	---	----------	---

22. Does this school have a separate room for a library/resource/media center?

Yes	74	96.10%	No	3	3.90%
-----	----	--------	----	---	-------

23. How does the size of your school's library/resource/media center compare with the size of a typical classroom in your building?

Smaller:	0	0.00%	About the same size:	7	9.33%	Larger:	68	90.67%
----------	---	-------	----------------------	---	-------	---------	----	--------

24. How many classrooms would fit in the space used for your library/resource/media center?

Minimum:	1	Maximum:	3	Median:	3	Average:	3
----------	---	----------	---	---------	---	----------	---

25. If you have a library/resource/media center, is it staffed by a licensed, professional librarian?

Yes	71	94.67%	No	4	5.33%
-----	----	--------	----	---	-------

26. What percent time is your library/resource/media center staffed by a licensed, professional librarian?

Number of schools reporting library/resource/media center staffed by licensed, professional librarian: 71

Minimum:	20%	Maximum:	100%	Median:	100%	Average:	84.04%
----------	-----	----------	------	---------	------	----------	--------

CESA: 10

Number of schools reported for CESA 10: 77

27. Does this school have a separate room for a parent/family center?

Yes 15 19.48% No 62 80.52%

28. How does the size of your school's parent/family center compare with the size of a typical classroom in your building?

Smaller: 11 73.33% About the same size: 3 20.00% Larger: 1 6.67%

29. How many classrooms would fit in the space used for the parent/family center?

Minimum: .75 Maximum: 2 Median: 1 Average: 1

B. SCHOOL SAFETY

30. Does your school have a "Locked Door" policy (doors can only be opened from the inside)?

Yes 24 31.17% No 53 68.83%

31. Does your school have a "Check-In" policy for school visitors?

Yes 72 93.51% No 5 6.49%

32. Does your school have an established emergency response plan for dealing with school safety issues?

Yes 75 97.40% No 2 2.60%

33. Does your school have on-site security provided by police officers or private security guards?

Yes 3 3.90% No 74 96.10%

34. Does your school have parent or other community volunteers to assist in monitoring the school?

Yes 3 3.90% No 74 96.10%

35. Does your school have metal detectors?

Yes 0 0.00% No 77 100.00%

36. Does your school have surveillance cameras located within the school building or on school grounds?

Yes 2 2.60% No 75 97.40%

C. EDUCATIONAL APPROPRIATENESS AND SUITABILITY**ELEMENTARY SCHOOLS ONLY**

Number of Elementary Schools Reported: 43

Educational Appropriateness:

38. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives.

Strongly agree with statement:	14	25.45%	Disagree with statement:	8	14.55%
Agree with statement:	32	58.18%	Strongly disagree with statement:	1	1.82%

39. Pre-kindergarten and Kindergarten space accommodates developmental range and needs of young children by providing a minimum of 35 square feet per occupant.

Strongly agree with statement:	11	20.37%	Disagree with statement:	4	7.41%
Agree with statement:	38	70.37%	Strongly disagree with statement:	1	1.85%

CESA: 10

Number of schools reported for CESA 10: 77

Number of Elementary Schools reported for CESA 10: 43

40. Adequate space is available for small work group instruction (less than 15 students).

Strongly agree with statement:	11	20.37%	Disagree with statement:	19	35.19%
Agree with statement:	23	42.59%	Strongly disagree with statement:	1	1.85%

41. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students.

Strongly agree with statement:	23	42.59%	Disagree with statement:	3	5.56%
Agree with statement:	28	51.85%	Strongly disagree with statement:	0	0.00%

42. Adequate space is available for large work group instruction (more than 30 students).

Strongly agree with statement:	6	11.11%	Disagree with statement:	20	37.04%
Agree with statement:	23	42.59%	Strongly disagree with statement:	5	9.26%

43. Equipment and furniture (such as shelving units, tables, and chairs) are the appropriate size for the building's student population.

Strongly agree with statement:	31	57.41%	Disagree with statement:	4	7.41%
Agree with statement:	19	35.19%	Strongly disagree with statement:	0	0.00%

Building Suitability for Education:

44. Buildings materials, color schemes, and decor provide impetus to learning.

Strongly agree with statement:	23	42.59%	Disagree with statement:	4	7.41%
Agree with statement:	27	50.00%	Strongly disagree with statement:	0	0.00%

45. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located.

Strongly agree with statement:	23	42.59%	Disagree with statement:	2	3.70%
Agree with statement:	29	53.70%	Strongly disagree with statement:	0	0.00%

46. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size.

Strongly agree with statement:	11	20.37%	Disagree with statement:	18	33.33%
Agree with statement:	24	44.44%	Strongly disagree with statement:	1	1.85%

47. Building is accessible to students with disabilities.

Strongly agree with statement:	20	37.04%	Disagree with statement:	3	5.56%
Agree with statement:	29	53.70%	Strongly disagree with statement:	2	3.70%

48. Space is available and appropriate for extended day learning opportunities, including before and after school day care.

Strongly agree with statement:	10	18.52%	Disagree with statement:	18	33.33%
Agree with statement:	24	44.44%	Strongly disagree with statement:	2	3.70%

School Site Suitability:

49. Site is large enough to meet educational needs and is accessible.

Strongly agree with statement:	17	31.48%	Disagree with statement:	6	11.11%
Agree with statement:	30	55.56%	Strongly disagree with statement:	1	1.85%

CESA: 10

Number of schools reported for CESA 10: 77

Number of Elementary Schools reported for CESA 10: 43

50. Site has a safe outdoor space where children can engage in a variety of games, sports, and motor activities.

Strongly agree with statement:	22	40.74%	Disagree with statement:	4	7.41%
Agree with statement:	28	51.85%	Strongly disagree with statement:	0	0.00%

51. Student loading areas are segregated from other vehicular traffic and pedestrian walkways.

Strongly agree with statement:	12	22.22%	Disagree with statement:	17	31.48%
Agree with statement:	24	44.44%	Strongly disagree with statement:	1	1.85%

Playground Site and Equipment Suitability:

52. Playground size is appropriate for number of students.

Strongly agree with statement:	21	38.89%	Disagree with statement:	8	14.81%
Agree with statement:	23	42.59%	Strongly disagree with statement:	2	3.70%

53. Playgrounds are separated from streets and parking areas with fencing or other permanent material.

Strongly agree with statement:	13	24.07%	Disagree with statement:	11	20.37%
Agree with statement:	27	50.00%	Strongly disagree with statement:	3	5.56%

54. Playgrounds are well equipped and appropriate for age levels.

Strongly agree with statement:	14	25.93%	Disagree with statement:	7	12.96%
Agree with statement:	32	59.26%	Strongly disagree with statement:	1	1.85%

55. Playground equipment is accessible to students with disabilities.

Strongly agree with statement:	7	12.96%	Disagree with statement:	19	35.19%
Agree with statement:	28	51.85%	Strongly disagree with statement:	0	0.00%

56. Playground equipment is free of sharp edges, of sound construction, and in good condition.

Strongly agree with statement:	27	50.00%	Disagree with statement:	3	5.56%
Agree with statement:	24	44.44%	Strongly disagree with statement:	0	0.00%

MIDDLE, JUNIOR HIGH, AND HIGH SCHOOLS ONLY

Number of Secondary Schools Reported: 34

Educational Appropriateness:

57. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives.

Strongly agree with statement:	9	24.32%	Disagree with statement:	4	10.81%
Agree with statement:	24	64.86%	Strongly disagree with statement:	0	0.00%

58. Size and design of special learning areas (science labs, art, technology education, music and special education) is compatible with instructional need.

Strongly agree with statement:	7	18.92%	Disagree with statement:	5	13.51%
Agree with statement:	24	64.86%	Strongly disagree with statement:	1	2.70%

59. Adequate space is available for small work group instruction (less than 15 students).

Strongly agree with statement:	6	16.22%	Disagree with statement:	5	13.51%
Agree with statement:	25	67.57%	Strongly disagree with statement:	1	2.70%

CESA: 10

Number of schools reported for CESA 10: 77

Number of Secondary Schools reported for CESA 10: 34

60. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students.

Strongly agree with statement:	11	29.73%	Disagree with statement:	2	5.41%
Agree with statement:	23	62.16%	Strongly disagree with statement:	1	2.70%

61. Adequate space is available for large work group instruction (more than 30 students).

Strongly agree with statement:	2	5.41%	Disagree with statement:	14	37.84%
Agree with statement:	19	51.35%	Strongly disagree with statement:	2	5.41%

Building Suitability for Education:

62. Buildings materials, color schemes, and decor provide impetus to learning.

Strongly agree with statement:	8	21.62%	Disagree with statement:	2	5.41%
Agree with statement:	26	70.27%	Strongly disagree with statement:	1	2.70%

63. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located.

Strongly agree with statement:	10	27.03%	Disagree with statement:	1	2.70%
Agree with statement:	25	67.57%	Strongly disagree with statement:	1	2.70%

64. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size.

Strongly agree with statement:	7	18.92%	Disagree with statement:	10	27.03%
Agree with statement:	17	45.95%	Strongly disagree with statement:	3	8.11%

65. Building is accessible to students with disabilities.

Strongly agree with statement:	10	27.03%	Disagree with statement:	2	5.41%
Agree with statement:	24	64.86%	Strongly disagree with statement:	1	2.70%

66. Space is available and appropriate for extended day learning opportunities, including before and after school day care.

Strongly agree with statement:	4	10.81%	Disagree with statement:	9	24.32%
Agree with statement:	22	59.46%	Strongly disagree with statement:	2	5.41%

School Site Suitability:

67. Site is large enough to meet educational needs and is accessible.

Strongly agree with statement:	15	40.54%	Disagree with statement:	5	13.51%
Agree with statement:	16	43.24%	Strongly disagree with statement:	1	2.70%

68. Site has a safe outdoor space where students can engage in a variety of games, sports, and motor activities.

Strongly agree with statement:	17	45.95%	Disagree with statement:	3	8.11%
Agree with statement:	17	45.95%	Strongly disagree with statement:	0	0.00%

69. Student loading areas are segregated from other vehicular traffic and pedestrian walkways.

Strongly agree with statement:	4	10.81%	Disagree with statement:	11	29.73%
Agree with statement:	19	51.35%	Strongly disagree with statement:	3	8.11%

End of Survey